
































# ASSEMBLING INSTRUCTION MT-7209

<b>A</b>  x1	<b>B</b>  x1	<b>C</b>  x2	<b>D</b>  x1	<b>E</b>  x1	<b>F</b>  x4	
<b>G</b>  x2	<b>H</b>  x2	<b>I</b>  x1	<b>J</b>  x1	<b>K</b>  x2	<b>L</b>  x1	
<b>M</b>  x6	<b>N1</b>  x4	<b>N2</b>  x1	<b>N3</b>  x1	<b>N4</b>  x2	<b>N5</b>  x1	
<b>N6</b>  x1	<b>O1</b>  x2	<b>O2</b>  x2	<b>O3</b>  x2	<b>O4</b>  x2	<b>P</b>  x2	
<b>Q1</b> GP-50  x16	<b>Q2</b> QK  x16	<b>R1</b> ESK-12  x6	<b>R2</b> ETK-10  x6	<b>S</b> GR-19F  x20	<b>T</b> GG-19F  x16	<b>U</b> FF  x1